

T-Con Boards

T420XW01 V9 (07A06-11)

BN41-00918b (FHD120FRC_EBGA)

BN41-00895B

40HDCP2LV0.3

LC420WX7 (6870C-01050B Ver.1.0)

UF320XB BUF320G040D1 Ver.A

UD320XA (PCD:BUD320G04051)

V420H1-C12

V320B1-C

LJ41-08392A (LJ92-01708A)

6870QCH006A (42V8&X3)

Sanyo DP26746 E114139

T315HW04 V0(31T09-C0G)

T260XW01 03A06-1E LC420WUN-SCA1 (6870C-0310A)

EAX39594101 (50G1_CTRL)

ANP2152-A

LJ92-01845A/B/C/D/E (59DF LM)

LM270WF1-TLA1-511

6870QCH0C6C (42V8&X3)

40/46/52HHC6LV3.5

6870C-0238B (LC320WXN-SBA1)

V270B1-L01-C

Netzteile:

FSP204-2F01(S07)

FSP204-2F01(S07)

FSP228-3F01

FSP223-3F01

0802-2304 R 0.8 02238

0802-2302 R 0.6

MK37P6T (BN44-00234A)

DPS-279BP A

EAX55176301/12

BN96-02581A

BN96-03833A

BN44-00232A IP-54135T

BN44-00445C (PB6F_WVL)

BN44-00197A

YP2204 REV_1.0

Mainboard

EAX60686904(2)

EAX54148403(0)

EAX40157601/17

EAX40150702(17)

Pnl 3139 123 63401v3 Bd 3139

BN41-00811B

BN41-01716A

BN41-007C4A (MP1.0)

BN41-00974B

BN41-00825A

BN41-00919A

BN41-01702A

17MB65-1 v.2 Vestel

715T2804-3

OPVP-0061 Rev:D

04P5541A-05-88

LG EAX42487505 (0)

Inverter:

6632L-0528A LC320WXN REV-1.3

ungetestet :

Main:

L6B Y51.190R-8 Beko

Z1J190R-6 Beko

EAX61073205 (0)

BN41-01028C

MF-056A 6870VM0531H (0)

BN41-00962A

Netzteil:

PSLF121401

PWI2004SPIA Rev.1.1

EADP-57CF B Rev.03

BN44-00213A

BN44-00329A (PSF301501A)

BN44-00167C

BN44-00195A

E247691

AIP0190A

IP-54135T

715T2804-3

OPVP-0061 Rev.D (EAY46912301)

Plasma TV:

6871QZ056B ZSus

E247691 Netzteil

42V50000_YDRV 6870QFE007C

42V50000_YDRV 6870QFE007B

Inverter:

Darfon V144 H4.V1448.331

P2714E01 Ver6.0

LC320WXN PNEL-T803A Rev.1.3

I270B1-12C.C001A

HPC-1518 (HIU-607)

E227809 A (VK8807010106)

SST320_4UA01